

Most extinguishers require an
extended service every fifth year

DISCHARGE AND REFILL

WHY REPLACE YOUR EXTINGUISHERS?



REPLACE? JUST REFILL

What is an extended service?

All extinguishers, to comply with British Standard 5306 except CO2 units, have to have an extended service every fifth year, the unit is discharged, tested and refilled with new medium - if compliant.

Very few companies actually carry out this extended service at site, often claiming environmental issues make this impossible. These companies choose to replace these extinguishers instead.

How is OHEAP different?

OHEAP follow the British Standards (BS3506 Part 9). Discharging on extended service dates at customer premises. You can even view this process yourself whilst we do it.

Our systems of work ensure all environmental issues are complied with and all waste is removed from site.

Our ethos is why replace a perfectly good extinguisher when it just needs an extended service.

What does this mean for you?

Firstly, it will drive down your carbon footprint as it reduces the number of extinguishers manufactured by not replacing them. It also means you get peace of mind that OHEAP is safely and environmentally disposing of the contents.

Secondly, it saves you money. Our discharge testing service increases the lifespan of your extinguishers; and the cost of replacement units is driven down as we'd only replace those units that fail the extended service.

Find out more from [David Moore](#) your local fire protection expert at DaveM@oheap.co.uk or call him on [07586 074993](tel:07586074993)