

You can find further information on our web page
www.denios.co.uk



To help you find the right fume protection mask and filter, see the table below to find the right combination to suit your requirements when wearing the mask

If the job you are looking for isn't in the list, ring our customer services department on 01952 811991.

Types of masks		disposable half mask, model 4000 plus	Reusable half masks, models 6000 and 7500	Full mask, model 6000	Half mask, model 100/2 BETA	Half mask POLIMASK 330	Full masks, models 607/607 TR/SPERA
		see p. 443	see p. 443	see p. 443	see p. 444	see p. 445	see p. 445
Job	Protection from	Type of filter	Type of filter	Type of filter	Type of filter	Type of filter	Type of filter
Stripping paint	organic solvents	A2P3	A2	A2P3	ABEK-P3	A2-P3	A2-P3
	Flash point > 65°C				ABEK-P3	ABEK-P3	ABEK-P3
	Sodium hydroxide	P3	P3	P3	ABEK-P3	ABEK-P3	ABEK-P3
	Aqueous solutions with over 5% Natrium hydroxide						
	Ammonia	ABEK-P3	ABEK-P3	ABEK2-P3	ABEK-P3	ABEK-P3	ABEK-P3
Insulation	Mineral fibres (glass/mineral wool)	P3	P3	P3	P3	P3	P3
Disinfecting, Chlorination	Chlorinelor	ABEK-P3	ABEK	ABEK2-P3	ABEK-P3	ABEK-P3	ABEK-P3
	Formaldehyde	ABEK-P3	ABEK-P3		ABEK-P3	ABEK-P3	ABEK-P3
	Organic solvents	A2P3	A2	A2	ABEK-P3	A2-P3	A2-P3
	Flash point > 65°C				ABEK-P3	ABEK-P3	ABEK-P3
Gluing (parquet flooring and carpets)	solvent based adhesives	A2P3	A2	A2	A1	A2	A2
			A2-P3	A2-P3		A2-P3	A2-P3
working with resin	Volatile compounds	A2P3	A2	A2		A2	A2
	(organic solvents)		A2P2	A2P3	ABEK	A2-P3	A2-P3
	Flash point > 65°C						
painting (spraying)	Paints containing solventse	A2P3	A2-P3	A2-P3	ABEK-P3	A2-P3	A2-P3
		A2P3	A2P2	A2P2	ABEK-P3	ABEK-P3	ABEK-P3
	Paint containing isocyanates	ABEK-P3	ABEK-P3	ABEK2-P3	ABEK-P3	ABEK-P3	ABEK-P3
	Water based paints (Paints containing weak solvents)	A2P3	A2P2	A2P3	A1	A2	A2
	Emulsion paints (solvent free)	A2P3	P2	P3	P3	P3	P3
Painting (decorating)	Paints containing solvents	A2P3	A2	A2	A1, ABEK-P3	A2, A2-P3, ABEK-P3	A2, A2-P3, ABEK-P3
	Dispersion paints, Water varnish	A2P3	P2	P3	P3	P3	P3
Pest control, Crop spraying	Aqueous solutions	A2P3	P2	P3	P3	P3	P3
	organic (volatile)	A2-P3	A2-P3	A2-P3	ABEK-P3	A2-P3	A2-P3
		ABEK-P3	ABEK-P3	ABEK2-P3	ABEK-P3	ABEK-P3	ABEK-P3
	Containing hydrocyanic acid	ABEK-P3	ABEK-P3	ABEK2-P3	ABEK-P3	ABEK-P3	ABEK-P3
Cleaning	Dust (inert, for example irritant)	A2P3	P2	P3	P3	P3	P3
	Unpleasant smells (for example Manure, sewage, excrement, gases of harmless concentrations)	ABEKP3	ABEK	ABEK	ABEK	A2-P3	A2-P3
	petroleum ether	A2P3	A2	A2	ABEK-P3	A2-P3	A2-P3
						ABEK-P3	ABEK-P3
	organic solvents, Flash point > 65°C, for example Universal or nitro thinners	A2P3	A2	A2	ABEK-P3	A2-P3	A2-P3
						ABEK-P3	ABEK-P3
	Acids, for example hydrochloric acid	ABEK-P3	ABEK-P3	ABEK2-P3	ABEK-P3	ABEK-P3	ABEK-P3
Welding	Fumes from welding, Non-alloy steel etc.	ABEK-P3	P3	P3	P3	P3	P3
	Fumes from welding Alloy steel	ABEK-P3	P3	P3	P3	P3	P3
	Fumes from welding dirty or coated steel sheet (welding for repair work)	ABEK-P3	ABEK-P3	ABEK-P3	ABEK-P3	ABEK-P3	ABEK-P3
	Fumes from welding, containing zinc	P3	P3	ABEK2-P3	P3	P3	P3